

904	P40AUTO	TC	MAKECADR	# HELLO THERE.
905		TS	TEMPR60	# FOR GENERALIZED RETURN TO OTHER BANKS.
906	P40A/P	TC	BANKCALL	# SUBROUTINE TO CHECK PGNCS CONTROL
907		CADR	G+N,AUTO# AND AUTO STABILIZATION MODES	
908		CCS	A	# +0 INDICATES IN PGNCS, IN AUTO
909		TCF	TURNITON	# + INDICATES NOT IN PGNCS AND/OR AUTO
910		CAF	APSFLBIT	# ARE WE ON THE DESCENT STAGE?
911		MASK	FLGWRD10	
912		CCS	A	
913		TCF	GOBACK	# RETURN
914		CAF	BIT5	# YES, CHECK FOR AUTO-THROTTLE MODE
915		EXTEND		
916		RAND	CHAN30	
917		EXTEND		
918		BZF	GOBACK	# IN AUTO-THROTTLE MODE -- RETURN
919	TURNITON	CAF	P40A/PMD	# DISPLAYS V50N25 R1=203 PLEASE PERFORM
920		TC	BANKCALL	# CHECKLIST 203 TURN ON PGNCS ETC.
921		CADR	GOPERF1	
922		TCF	GOTOP00H	# V34E TERMINATE
923		TCF	P40A/P	# RECYCLE
924	GOBACK	CA	TEMPR60	
925		TC	BANKJUMP	# GOODBYE. COME AGAIN SOON.